



PART NO.	"A"	"B"	"C"
LWS-SE2-1-01	.27 (6.9)	.38 (9.7)	.67 (17.0)
LWS-SE2-2-01	.40 (10.2)	.53 (13.5)	.82 (20.8)



TO FIT IN A $.187 \pm .003$
(4.75 ± 0.08) DIA. HOLE, IN A
.020-.063 (0.5-1.6) THICK PANEL.

NOTES:

1. MATERIAL: NYLON 6/6 (RMS-01).
FLAME RETARDANT NYLON (RMS-19)
AVAILABLE BY SPECIAL ORDER.
2. COLOR: NATURAL.

TITLE: LOCKING WIRE SADDLE SIDE ENTRY (UK)					DWG IN IN (MM)	
TOLERANCES UNLESS NOTED .XX= $\pm .010$.XXX= $\pm .005$ FRAC= $\pm 1/64$ ANG= $\pm 1^\circ$	FILE # LWS-SE2	DWN: P.B.	APP:	FINAL		
	MAT'L: SEE NOTES	DT: 08-25-94	DT:	PART #		
	RE: RICHCO, INC.	RICHCO INC. PO BOX 804238, CHICAGO, 60680 (773) 539-4060		SEE TABLE		
REV	DESCRIPTION	ENGR	DATE	PRINT TYPE CA		

C	ADDED -01 TO PART # & CHANGED NOTE 1	SJ 03.27.02
B	CHANGED FILE NO. AND ADDED TOL TO HOLE DIA.	SM 03.20.02
A	.187 DIA. HOLE WAS .189	PB 102694
REV	DESCRIPTION	ENGR DATE